	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comments	ErrorDefinition	Er
1	IS&R	L2	3196	(385/31,49,83,88,89,9 0,91).CCLS.	USPA T; EPO; JPO; DERW ENT	2002/05/3 0 13:17			0
2	BRS	L3	1	optoelectronic with ((fiber adj array) and V-groove\$1 and VCSEL)	i	2002/05/3 0 13:20			0
3	BRS	L5	1	optoelectronic with (V-groove\$1 and VCSEL)	1	2002/05/3 0 13:21		***************************************	0
4	BRS	L4	1	optoelectronic with (fiber and V-groove\$1 and VCSEL)	i	2002/05/3 0 13:21	3		O
5	BRS	L6	21	optoelectronic with (fiber and V-groove\$1)		2002/05/3 0 13:22	3		0
6	BRS	L8	6	optoelectronic with SiO2	USPA T; EPO; JPO; DERW ENT	2002/05/3 0 13:23	3		0

09/827,183

	Туре	L#	Hits	Search Text	DBs	Time Stamp	m m e	Errors
7	BRS	L9	1	optoelectronic with Al203	USPA T; EPO; JPO; DERW ENT	2002/05/3 0 13:23	3	0